

United States Steel Corporation Clairton Works 400 State Street Clainton, PA 15025

May 17, 2004

Dr. Roger C. Westman Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Fittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Assistant Council Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Steve Hepler

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 04-0079

ACHD Reference Number: N/A

100 Carbonate Unit USS Clairton Works

## Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac Plant Manager Clairton Works

## NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- USS Reference Number: 04-0079
  ACHD Reference Number: N/A
- 2. Date & Time of Breakdown: Date: 05/16/04 Time: 1455 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: 100 Carbonate Unit
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: Intermittent operational problems stabilizing the stripper following the start-up of the 100 Carbonate Unit, resulted in coke oven gas by-passing through the Sulfur Plant. This is a continuation of the incident which was previously reported under USS Reference Number: 04-0077 & 04-0078.
- 8. Identification of Emissions:
  - A. Type(s) (CO, NOX,  $SO_2$ , Particulates, Hydrocarbons, etc.) Intermittent elevated  $H_2S$  in the down river gas line system, causing increased  $SO_2$  at point of combustion.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO<sub>2</sub> is an eye, nose, and throat irritant.
  - C. Amount of each type emitted (or likely to be emitted). Light
  - 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). Continuous system monitoring is being performed until the stripper is stabilized.
- 10. Facility back in operation Date: 05/16/04 Time: 2112 hours

Signature (lewh. Aurs Date 5/18/04 Coleen M. Davis

Senior Environmental Control Engineer Phone: 233-1015